

Fig. 2




Fig. 3




Fig. 4





Fig. 5



ì

Fig. 6

(A)

S1	
POSITION OF REF. POINT	X1, Y1
CORRECTION ANGLE 0	- 0.1 DEG.
NUMBER OF SX	3
GAP BETWEEN SX	15mm
NUMBER OF SY	1
GAP BETWEEN SY	7mm

(B)

\$2	
POSITION OF REF. POINT	X2, Y2
CORRECTION ANGLE 0	- 0.2 DEG.
NUMBER OF SX	3
GAP BETWEEN SX	15mm
NUMBER OF SY	1
GAP BETWEEN SY	7mm

(C)

\$3	
POSITION OF REF. POINT	X3, Y3
CORRECTION ANGLE 0	- 0.3 DEG.
NUMBER OF SX	3
GAP BETWEEN SX	15mm
NUMBER OF SY	1
GAP BETWEEN SY	7mm

Fig. 7

(A)

S1		
CPS	COORDINATE	
S1 - 1	x1,	у1
S1 - 2	x1,	y1 + 15
S1 - 3	×1,	y1 + 30
S1 - 4	x1,	y1 + 45
S1 - 5	$\times 1 + 7$	
S1 - 6	$\times 1 + 7$	
S1 - 7	$\times 1 + 7$	
S1 - 8	x1 + 7	, y1 + 45

(B)

\$2		
CPS	COORDINATE	
S2 - 1	x2,	у2
S2 - 2	x2,	y2 + 15
S2 - 3	x2,	y2 + 30
S2 - 4	x2,	y2 + 45
S2 - 5	x2 +	7, y2
S2 - 6	x2 +	7, y2 + 15
S2 - 7	x2 +	7, y2 + 30
S2 - 8	x2 +	7, $y2 + 45$

(C)

\$3		
COORDINATE		
х3, у3		
x3, y3 + 15		
x3, y3 + 30		
x3, y3 + 45		
x3 + 7, y3		
x3 + 7, $y3 + 15$		
x3 + 7, $y3 + 30$		
x3 + 7, $y3 + 45$		